



NSAI
Standards

Irish Standard
I.S. EN 15305:2008

Non-destructive Testing - Test Method for Residual Stress analysis by X-ray Diffraction

I.S. EN 15305:2008

Incorporating amendments/corrigenda issued since publication:

<i>This standard replaces:</i>	<i>This standard is based on:</i> EN 15305:2008	<i>Published:</i> 13 August, 2008	
This Irish Standard was published under the authority of the NSAI and comes into effect on: 17 September, 2008		ICS number: 19.100	
NSAI 1 Swift Square, Northwood, Santry Dublin 9	T +353 1 807 3800 F +353 1 807 3838 E standards@nsai.ie W NSAI.ie	Sales: T +353 1 857 6730 F +353 1 857 6729 W standards.ie	Price Code: X
Údarás um Chaighdeáin Náisiúnta na hÉireann			

ICS 19.100

English Version

Non-destructive Testing - Test Method for Residual Stress analysis by X-ray Diffraction

Essais non-destructifs - Méthode d'essai pour l'analyse des
contraintes résiduelles par diffraction des rayons X

Zerstörungsfreie Prüfung - Röntgendiffraktometrisches
Prüfverfahren zur Ermittlung der Eigenspannungen

This European Standard was approved by CEN on 4 July 2008.

CEN members are bound to comply with the CEN/CENELEC Internal Regulations which stipulate the conditions for giving this European Standard the status of a national standard without any alteration. Up-to-date lists and bibliographical references concerning such national standards may be obtained on application to the CEN Management Centre or to any CEN member.

This European Standard exists in three official versions (English, French, German). A version in any other language made by translation under the responsibility of a CEN member into its own language and notified to the CEN Management Centre has the same status as the official versions.

CEN members are the national standards bodies of Austria, Belgium, Bulgaria, Cyprus, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Romania, Slovakia, Slovenia, Spain, Sweden, Switzerland and United Kingdom.



EUROPEAN COMMITTEE FOR STANDARDIZATION
COMITÉ EUROPÉEN DE NORMALISATION
EUROPÄISCHES KOMITEE FÜR NORMUNG

Management Centre: rue de Stassart, 36 B-1050 Brussels

Contents

Page

Foreword.....	5
Introduction	6
1 Scope	7
2 Normative references	7
3 Terms, definitions and symbols.....	8
3.1 Terms and definitions	8
3.2 Symbols and abbreviations	8
4 Principles	10
4.1 General principles of the measurement	10
4.2 Biaxial stress analysis	12
4.3 Triaxial stress analysis	13
5 Specimen	14
5.1 Material characteristics	14
5.1.1 General.....	14
5.1.2 Shape, dimensions and weight	15
5.1.3 Specimen composition/homogeneity.....	15
5.1.4 Grain size and diffracting domains	16
5.1.5 Specimen X-ray transparency	16
5.1.6 Coatings and thin layers	16
5.2 Preparation of specimen	17
5.2.1 Surface preparation	17
5.2.2 Stress depth profiling.....	17
5.2.3 Large specimen or complex geometry	17
6 Equipment	17
6.1 General.....	17
6.2 Choice of equipment	18
6.2.1 General.....	18
6.2.2 The ω -method.....	19
6.2.3 The χ -method	20
6.2.4 The modified χ -method	21
6.2.5 Other geometries	21
6.3 Choice of radiation	21
6.4 Choice of the detector.....	23
6.5 Performance of the equipment.....	24
6.5.1 Alignment	24
6.5.2 Performance of the goniometer	24
6.6 Qualification and verification of the equipment	24
6.6.1 General.....	24
6.6.2 Qualification	24
6.6.3 Verification of the performance of the qualified equipment	26
7 Experimental Method	27
7.1 General.....	27
7.2 Specimen positioning	27
7.3 Diffraction conditions.....	28
7.4 Data collection	29
8 Treatment of the data	30
8.1 General.....	30
8.2 Treatment of the diffraction data.....	30
8.2.1 General.....	30

8.2.2	Intensity corrections	30
8.2.3	Determination of the diffraction line position.....	31
8.2.4	Correction on the diffraction line position.....	32
8.3	Stress calculation.....	32
8.3.1	Calculation of strains and stresses.....	32
8.3.2	Errors and uncertainties [16], [17].....	33
8.4	Critical assessment of the results	34
8.4.1	General	34
8.4.2	Visual inspection.....	34
8.4.3	Quantitative inspection.....	34
9	Report	35
10	Experimental determination of XECs	36
10.1	Introduction.....	36
10.2	Loading device	37
10.3	Specimen.....	37
10.4	Loading device calibration and specimen accommodation	38
10.5	Diffractometer measurements	38
10.6	Calculation of XECs	38
11	Reference specimens.....	39
11.1	Introduction.....	39
11.2	Stress-free reference specimen.....	39
11.2.1	General	39
11.2.2	Preparation of the stress-free specimen.....	39
11.2.3	Method of measurement	40
11.3	Stress-reference specimen	40
11.3.1	Laboratory qualified (LQ) stress-reference specimen.....	40
11.3.2	Inter-laboratory qualified (ILQ) stress-reference specimen.....	41
12	Limiting cases.....	41
12.1	Introduction.....	41
12.2	Presence of a subsurface stress gradient.....	42
12.3	Surface stress gradient.....	42
12.4	Surface roughness	42
12.5	Non-flat surfaces	42
12.6	Effects of specimen microstructure	43
12.6.1	Textured materials.....	43
12.6.2	Multiphase materials	43
12.7	Broad diffraction lines	44
Annex A	(informative) Schematic representation of the European XRPD Standardisation Project	46
Annex B	(informative) Sources of Residual Stress	47
B.1	General	47
B.2	Mechanical processes	47
B.3	Thermal processes.....	47
B.4	Chemical processes.....	47
Annex C	(normative) Determination of the stress state - General Procedure.....	48
C.1	General	48
C.2	Using the exact definition of the deformation.....	49
C.2.1	General	49
C.2.2	Determination of the stress tensor components	49
C.2.3	Determination of θ and d_0	50
C.3	Using an approximation of the definition of the deformation.....	50
C.3.1	General	50
C.3.2	Determination of the stress tensor components	51
C.3.3	Determination of θ_0 and d_0	51
Annex D	(informative) Recent developments.....	52
D.1	Stress measurement using two-dimensional diffraction data.....	52
D.2	Depth resolved evaluation of near surface residual stress - The Scattering Vector Method.....	54

D.3	Accuracy improvement through the use of equilibrium conditions for determination of stress profile	55
Annex E	(informative) Details of treatment of the measured data	56
E.1	Intensity correction on the scan	56
E.1.1	General.....	56
E.1.2	Divergence slit conversion	56
E.1.3	Absorption correction	57
E.1.4	Background correction	58
E.1.5	Lorentz-polarisation correction.....	58
E.1.6	K-Alpha2 stripping.....	59
E.2	Diffraction line position determination.....	59
E.2.1	Centre of Gravity methods.....	59
E.2.2	Parabola Fit	60
E.2.3	Profile Function Fit	60
E.2.4	Middle of width at x% height method	61
E.2.5	Cross-correlation method	61
E.3	Correction on the diffraction line position	61
E.3.1	General.....	61
E.3.2	Remaining misalignments	61
E.3.3	Transparency correction.....	62
Annex F	(informative) General description of acquisition methods	64
F.1	Introduction	64
F.2	Definitions	64
F.3	Description of the various acquisition methods	67
F.3.1	General method.....	67
F.3.2	Omega (ω) method	68
F.3.3	Chi (χ) method.....	69
F.3.4	Combined tilt method (also called scattering vector method).....	71
F.3.5	Modified chi method.....	73
F.3.6	Low incidence method	76
F.3.7	Modified omega method	77
F.3.8	Use of a 2D (area) detector	78
F.4	Choice of Φ and Ψ angles	79
F.5	The stereographic projection	80
Annex G	(informative) "Normal Stress Measurement Procedure" and "Dedicated Stress Measurement Procedure".....	82
G.1	Introduction	82
G.2	General.....	82
G.2.1	Introduction	82
G.2.2	Normal stress measurement procedure for a single specimen.....	82
G.2.3	Dedicated Stress Measurement Procedure for very similar specimens.....	82
	Bibliography.....	84

This is a free preview. Purchase the entire publication at the link below:

[Product Page](#)

-
- [Looking for additional Standards? Visit Intertek Inform Infostore](#)
 - [Learn about LexConnect, All Jurisdictions, Standards referenced in Australian legislation](#)
-