



National Standards Authority of Ireland

IRISH STANDARD

I.S. EN 60950:2001

ICS 35.020
35.260.10

National Standards
Authority of Ireland
Dublin 9
Ireland

Tel. (01) 807 3800
Tel: (01) 807 3838

**SAFETY OF INFORMATION TECHNOLOGY
EQUIPMENT**


*This Irish Standard was
published under the
authority of the National
Standards Authority of
Ireland
and comes into effect on:
August 17, 2001*

**NO COPYING WITHOUT NSAI
PERMISSION EXCEPT AS
PERMITTED BY COPYRIGHT
LAW**

© NSAI 2001

Price Code AK

Údarás um Chaighdeán Náisiúnta na hÉireann



Corrigendum to EN 60950:2000

English version

Title page

In the English title, **replace** in the reference of the IEC corrigendum "February" by "January".
In the French title, **replace** in the reference of the IEC corrigendum "février" by "janvier".
In the German title, **replace** in the reference of the IEC corrigendum "February" by "Januar".

2.10.2, text of IEC 60950:1999

In the first line, **replace** "(see also 1.4.7)" by "(see also 1.4.8)".

3.2.5

Replace the last paragraph of the common modification by:

In NOTE 1 to table 3B, **delete** the second sentence.

5.3.6, text of IEC 60950:1999

In the note, **replace** "4.4.3" by "4.7.3".

Annex Q, text of IEC 60950:1999

Replace the title of IEC 61032 by "Protection of persons and equipment by enclosures - Probes for verification".

Annex ZA

In the reference to IEC 60050-195, **replace** "Chapter" by "Part".

In the reference to IEC 60695-2-1/1, **replace** "EN 60695-2-2/1" by "EN 60695-2-1/1".

In the reference to IEC 60825-1, **add** in columns 4 and 5 after A11 "+ corr. July" and "1997".

February 2002

Publication 60950 de la CEI
(Troisième édition – 1999)

IEC Publication 60950
(Third edition – 1999)

**Sécurité des matériels de traitement
de l'information**

**Safety of information technology
equipment**

CORRIGENDUM 1

SOMMAIRE

Applies to French text only.

Page 20

Au lieu de:

Annexe C (normative) Essais des moteurs
dans les conditions anormales (voir 4.7.2.2
et 5.3.2)

Lire:

Annexe C (normative) Transformateurs
(voir 1.5.4 et 5.3.3)

Page 60

Applies to French text only.

1.2.8.7

Au lieu de:

...le courant dissipé ne soit pas dangereux.

Lire:

...le courant que peut débiter la source ne
soit pas dangereux.

Page 120

Applies to French text only.

Figure 2D

Au lieu de:

**Tension maximale permise après un
premier défaut**

Lire:

**Tensions maximales admises après un
premier défaut**

Correction en anglais seulement.

Page 131

Table 2C

Instead of:

**Output
current²⁾**
(I_{oc})

Read:

**Output
current²⁾**
(I_{sc})

Page 178

Applies to French text only.

Tableau 2J, colonnes 1, 2 et 3

Au lieu de:

TENSION DE SERVICE maximale

Lire:

TENSION DE SERVICE CRÊTE maximale

Page 242

Page 243

4.2.5 Essai de choc

4.2.5 Impact test

Troisième alinéa, deuxième ligne

Third paragraph, second line

Au lieu de:

Instead of:

...distance verticale de (H) (voir figure 4A).

...vertical distance (H) (see figure 4A).

Lire:

Read:

...hauteur verticale (H) de 1,3 m
(voir figure 4A).

...vertical distance (H) of 1,3 m
(see figure 4A).

Page 340

Page 341

A.2.7 Essai en remplacement

A.2.7 Alternative test

Deuxième ligne

Second line

Au lieu de:

Instead of:

...de la CEI 60695-2-2:1980

...of IEC 60695-2-2:1980

Lire:

Read:

...de la CEI 60695-2-2:1991

...of IEC 60695-2-2:1991

This is a free preview. Purchase the entire publication at the link below:

[Product Page](#)

-
- [Looking for additional Standards? Visit Intertek Inform Infostore](#)
 - [Learn about LexConnect, All Jurisdictions, Standards referenced in Australian legislation](#)
-